ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0628, W0675, W0520	5th Crs, NA	Amruthanagara 'B' Sector Cross Roads
Segment No.	**Total Length (m)**	
7/S-W0628/S113001	311.58	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	156.04	77.602468	13.061702	77.602447	13.060292	I0494	DEAD END
2	155.54	77.597774	13.054860	77.599163	13.054523	W0819	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements of Roads and Drain in Amruthanagara 'B' Sector Cross Roads inward no 07 Byatarayanapura Kodigehalli Sub-Division Yelahanka zone	5000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements of Roads and Drain in Amruthanagara 'B' Sector Cross Roads inward no 07 Byatarayanapura Kodigehalli Sub-Division Yelahanka zone	007-15-000065
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/360/2014-15	24/03/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/04/2015	26/04/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SAMBASHIVA		0.00
Phone No.	**E-Mail ID**	

9035637741

Field Inspection Details

Number of Trees	Any Other Information	Name
12		BASAVARAJU
Date of Inspection	**Remarks**	
24/01/2017	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0628, W0675, W0520

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	25/01/2017	23/02/2017	COMPLETED
SE	VASU K M	25/01/2017	23/02/2017	COMPLETED
EE	SRINIVAS REDDY	25/01/2017	23/02/2017	COMPLETED
AEE	RAJINIKANTH MALLI	25/01/2017	23/02/2017	COMPLETED
AE	BASAVARAJU	24/01/2017	23/02/2017	COMPLETED
AE	BASAVARAJU	24/01/2017	23/02/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0628, W0675, W0520